MARKER No. 12: ? DYER (d. 1856) daughter of D. & S. Dyer

EXISTING CONDITIONS

- The marble headstone is in poor condition: it is experiencing biological growth and staining and the inscriptions are not clearly legible.
- The headstone appears to be broken in half, with the lower portion lying on the ground and the upper loosely set in a damaged sandstone base. The lower fragment is weathered at the fracture line.
- The marker is surrounded by vegetation and the exact condition of the sandstone base is unknown.







After (September 209)

TREATMENT SUMMARY

- A. Excavation/Fragment Recovery
 - 1. Carefully remove marble headstone and sandstone base (and fragments).
 - 2. Cut back vegetation.
- ► the match to the lower marker fragment was not located.
- ► found intact sandstone base.
- B. Cleaning
 - 1. For removal of biological growth and general soiling, clean the marble headstone and sandstone base with D/2 Architectural Antimicrobial.
 - a. Clean water at low pressure (max 400 psi) and hand-pump sprayer.
 - b. Natural and nylon bristle brushes (varying stiffness and size).
 - c. Avoid dissolution or erosion of the stone.
- C. Re-attachment and Repair
 - 1. Attempt to re attach lower marble headstone fragment using two part stone epoxy and threaded brass rods.

► the small marble fragment (*Elmira*) does not appear to be a match to the larger, lower portion, therefore, the fragments were not re-attached. The *Elmira* fragment was laid against the re-set marker.

2. Point and patch marble headstone where necessary with custom mixed, lime based, marble repair mortar.

3. Repair sandstone base.

► cut new notch (mortise) in found sandstone base.

- D. Reset and Level
 - 1. Reset and level sandstone base upon compacted gravel.
 - 2. Reset and plumb marble headstone [fragment] into slotted sandstone base with Type O mortar. Point resultant joint with Type O mortar.
- E. Site Preparation and Repair
 - 1. Place pea gravel around base