

**MARKER No. 02: WALTER CREES. (d. 1908)**

---

**EXISTING CONDITIONS**

- The marble headstone and base are in good condition.
- The marble headstone and base are stained and contain biological growth.
- The marker has settled and is no longer plumb and level.



*Before (July 2009)*



*After (September 2009)*

**TREATMENT SUMMARY**

- A. Excavation/Fragment Recovery
1. Remove marker from ground.
  2. Excavate for new compacted gravel foundation.
- B. Cleaning
1. For removal of biological growth and general soiling, the marble headstone and base are to be cleaned with D/2 Architectural Antimicrobial.
    - a. Clean water at low pressure (max 400 psi) and hand-pump sprayer.
    - b. Natural or nylon bristle brushes.
    - c. Avoid dissolution or erosion of the stone.
- C. Re-attachment and Repair
- D. Reset and Level
1. Reset the base to proper depth, level and plumb, upon a new compacted gravel foundation.
  2. Reset the headstone to the base upon a thin bed of lime-based mortar and an outer bead of setting compound.
- E. Site Preparation and Repair
1. Place pea gravel at base of marker.