

**MARKER No. 26:**

---

**EXISTING CONDITIONS**

- The marker is in poor condition.
- The upper portion of the marble marker has broken off and its location is not currently known (the lower portion is secure in its sandstone base).
- The marble is severely weathered and sugaring, and the partial inscriptions are not legible.
- The monument has settled and the base is covered by deposition.
- The marble is experiencing slight biological growth and staining.



*Before (July 2009)*



*After (September 2009)*

**TREATMENT SUMMARY**

A. Excavation/Fragment Recovery

1. Cut back vegetation.
2. Carefully excavate around marker and remove from the ground.
3. Excavate ground in preparation for new compacted gravel foundation.
  - ▶ the upper portion of the marble marker was not located.
  - ▶ uncovered carved/moulded sandstone base

B. Cleaning

1. For removal of biological growth and general soiling, clean the marble portions and sandstone base with D/2 Architectural Antimicrobial.
  - a. Clean water at low pressure (max 400 psi) and hand-pump sprayer.
  - b. Natural and nylon bristle brushes (varying stiffness and size).
  - c. Avoid dissolution or erosion of the stone.

C. Re-attachment and Repair

D. Reset and Level

- a. Reset marker upon a foundation of compacted gravel to a depth which exposes the carved moulding detail. Ensure top of sandstone base is level.

E. Site Preparation and Repair

1. Replace soil around base.