


MARKER No. 30:FRENCH FAMILY GROUP-Cyrus E:1883; Sarah J (Stebbins):1894; James H:1898; Timothy B:1874

EXISTING CONDITIONS

- Overall, the monuments and markers are in good condition (the larger granite monument is likely a contemporary replacement).
- The family group is surrounded by encroaching and invasive vegetation (there is extensive woody plant growth and root development at the north end of the group).
- The small individual markers are slightly displaced and leaning to the east.
- The northern-most marker appears to be military issue, however, the inscriptions are not legible.



Before (July 2009)



After (September 2009)

TREATMENT SUMMARY

- A. Excavation/Fragment Recovery
 - 1. Cut back vegetation.
- B. Cleaning
 - 1. ~~For removal of biological growth and general soiling, clean the marble portions and sandstone base with D/2 Architectural Antimicrobial.~~
 - ▶ dry brush markers after cutting back vegetation.
- C. Re-attachment and Repair
 - ▶ assess and document condition of monument and markers.
- D. Reset and Level
- E. Site Preparation and Repair